(C) LUBIE CROWN SCREWS - & RUN TO TEST

NOTE: POWER BOOWN WORKS NORMAL UNIVESS

FLOW CONTROLL WALKE IS OPENED MORE THAN

3/45

A AUGER DUERIDE SWITCHES

- SWITCHES WORK WITH OUT REMOTE CONTROL ATTCHED PROVIDING JUMPER BAYS ARE INSTALLED ON CONTROLL BOX: THESE BAYS-CAPS FARE INCLUSE. WITH THE REMOTE CONTROLL KIT.

(B) HAND CRANKS | THICKNESS SCREWS - NORMAL EFFOR,
REQUIRED - CHECK CLUTCHES ETC. ON

NOTE: INSALLATION OF LOUER SCREW OPTION WILL

ALLOW EFFORTLESS TERRING


Q) CLEAN MACHINE


DER RIH TRACK TENSION ADJUSTING GUINDER
NOTE: THIS CYLLIOSER HAS BEEN ALEAKING FLUID

THE BREATHER SINCE MITTAL POT LEAK

WARDANTY HAS GOT PROGRESSIVELY WORSE,

...





ACCOUNT NUMBER INVOICE NBR INVOICE DATE 790-100495

641-02984 07/31/03

DUE DATE 08/30/03 TOTAL DUE \$1,804.43

AMOUNT PAID

MAIL REMITTANCE TO:

S INGERSOLL-RAND COMPANY

O T BLAW KNOX (919)

L O 750 BROADWAY AVENUE EAST

MATTOON IL 61938-0000

INGERSOLL-RAND EQUIPMENT SALES P O BOX 75697

CHARLOTTE NC 28275

INGERSOLL-RAND EQUIPMENT SALES

O R 300 TURNPIKE RD RTE9

SOUTHBORO MA 01772

CUSTOMER P.O. NBR.

ITEM NUMBER

D M TEL: (508) 481-1350

H T

I O Р

641-02984

INVOICE NO. INVOICE DATE ACCOUNT NBR. 07/31/03

790-100495

ORDER NO 641-5388 W

1,275.00

DESCRIPTION QUANTITY UNIT-PRICE

TOTAL AMOUNT 20311833 CYLINDER, TR 1.0 187.52 187.52 SHOP LABOR 20.0

> SUB-TOTAL 1,462.52 FREIGHT 10.14

63.75

TOTAL DUE 1,472.66

REMOVE ASPHALT FROM SCREED TRAILING EDGE INSTALL SHIMS TORQUE NUTS AND STRING LINE FOR FLATNESS. R/H AUGER TUNNEL EXTENSION REPAIR AND INSTALL STOP BLOCK STRAIGHTEN WELD AND REPAIR CENTRAL CHAIN STRIP AND INSTALL REMOVE ASPHALT FROM SPILL PLATE AREA TO FACILITATE INSTALLATION. R/H ARM REST. INSTALL NEW ROLL PIN AND REINSTALL. R/H AUGER CLEAN AND INSTALL MISSING SHORT AUGER SEGMENT SEE CUSTOMER W/O. 641-5426. REMOVE R/H END GATE AND CLEAN STRAIGHTEN GATE AND FRAME WELD BROKEN REAR PIN EDGER SKI AND REINSTALL.

LUBE CROWN SCREWS AND RUN TO TEST. NOTE: POWER CROWN WORKS NORMAL UNLESS FLOW CONTROL VALVE IS OPENED MORE THAN 3/4'S.

AUGER OVERRIDE SWITCHES. SWITCHES WORK WITH OUT REMOTE CONTROL ATTACHED PROVIDING JUMPER CAPS ARE INSTALLED ON CONTROL BOX. THESE CAPS ARE INCLUDED WITH THE REMOTE CONTOL KIT. HAND CRANKS/THICKNESS SCREWS

CONTINUED ON THE FOLLOWING PAGE

PAGE

1

ITEM NUMBER

DESCRIPTION QUANTITY UNIT-PRICE

TOTAL AMOUNT

NORMAL EFFORT REQUIRED. CHECK CLUTCHES ETC. ON NOTE: INSTALLATION OF ROLLER SCREW OPTIO WILL ALLOW EFFORTLESS TURNING. CLEAN MACHINE. REMOVE AND REPLACE TRACK TENSION ADJUSTING CYLINDER NOTE: THIS CYLINDER HAS BEEN BYPASSING LEAKING FLUID FROM THE BREATHER SINCE INITAL PDI LEAK HAS BEEN GETTING WORSE.

FAILURE DATE -7/23/ 3 REPAIR DATE - 7/31/3 IN SERVICE - 5/5/3 HOUR METER - 2

SERIAL NBR:6413441032-14 MODEL:PF-4410 DESCR:

CERTIFIED TO BE A TRUE AND CORRECT COPY

PAGE

2



Ingersoll-Rand Equipment and Services Company 300 Turnpike Road Southboro, MA 01772 508-481-1350

Work Order 58 TECH:

CUSTOMER: / A	
CALL LOCATION: Jarranty	CONTACT NAME:
DATE W/O OPENED:	PHONE NUMBER
MODEL: 9/30-/03	PO NUMBER
PF4410 HOURS: 298	S/N: 441032-14
Drass	

DESCRIPTION OF WORK PERFORMED:

DESCRIPTION OF WORK PERFORMED:
Leaking track Cylinder.
- RER LIHTRAK AWISTING CHI
- Stram Ou our OF LIH-TOOOL
- July
DONE
AT YOUR REQUEST, INGERSOLL-RAND AGREES TO PERFORM THE ARM

AT YOUR REQUEST, INGERSOLL-RAND AGREES TO PERFORM THE ABOVE SPECIFIED REPAIR WORK, MINIMUM CHARGE WILL BE 1 HOUR AT CURRENT LABOR RATES. IF THE NECESSITY FOR ANY FURTHER REPAIR IS DISCOVERED IN THE COURSE OF COMPLETING THE WORK, YOU WILL BE ADVISED OF THIS AS WELL AS THE ADDITIONAL COST. UNLESS AGREED TO OTHERWISE IN ADVANCE, THE TOTAL AMOUNT DUE WILL BE PAID IN FULL AT THE TIME THE EQUIPMENT IS PICKED UP. IF REQUIRED, YOU WILL BE RESPONSIBLE FOR ANY TRANSPORTATION OF YOUR EQUIPMENT TO AND FROM OUR SHOP, WE WILL ALLOW FIVE (5) DAYS AFTER YOU ARE NOTIFIED OF COMPLETION OF REPAIRS TO PICK UP THE EQUIPMENT. AFTER THIS TIME STORAGE CHARGES MAY BE ASSESSED. EQUIPMENT DESIGN CORRECTIONS OR MODIFICATIONS ARE NOT COVERED BY THIS CONTRACT. UNLESS EXPRESSLY AGREED TO OTHERWISE IN WRITING AND ATTACHED HERETO, THE REPAIR WORK SHALL

THERBY AGREE TO PAY ON DELIVERY FOR ALL LABOR, REPAIR PARTS AND MATERIAL USED AT YOUR CURRENT RATES IN PERFORMING THE

THE UNDERSIGNED CERTIFIES THAT HE HAS THE AUTHORITY TO BIND THE ABOVE NAMED OWNER BE IT A CORPORATION, PARTNERSHIP, OR PROPRIETORSHIP AS TO ALL NECESSARY CHARGES WITH RESPECT TO THE ABOVE REPAIRS

X	
AMMER OF	AGENT'S SIGNATURE

QUANTITY	PART #	DESCRIPTION
		DESCRIPTION 1
	/	Overnight X RF5669
~/V	00112-709-00	Tout
		THE MENSION CHUNDS
	 	
	1	
-		
	 	
		ger."
~ <u>-</u>		Service of Contraction of the Co
	Control of the Contro	
		_

INVOICE/CREDIT MEMO: 641-03408 10/28/03

INGERSOLE-RAND EQUIPMENT SALES

300 TURNPIKE RD RTE9 SOUTHBORO

MA 01772

I-R ORDER NBR:

ORIGINAL INVOICE NBR:

INVOICE DATE:

TEL: (508) 481-1350

641-5877 W

DATE SHIPPED:

VIA:

PREPAID

TERMS: NET 30 DAYS

CUST PO NBR: SHIP FROM:

INGERSOLL-RAND EQUIPMENT SALES

P O BOX 75697

CHARLOTTE

NC 28275

CUSTOMER NBR: 790-100495

TAX: 39-02-00-00.000 T4

INGERSOLL-RAND COMPANY

BLAW KNOX (919)

750 BROADWAY AVENUE EAST

MATTOON

IL 61938

00000

PART NUMBER / DESCRIPTION PCODE

QUANTITY UNIT PRICE DISCOUNT TOTAL AMOUNT

LEAKING TRACK CYLINDER. REMOVED AND REPLACED L/H

TRACK ADJUSTING CYL. STEAM OIL OUT OF L/H TRACK. 9/30/3

FAILURE DATE -

REPAIR DATE -10/20/ 3 5/ 5/ 3 IN SERVICE -

HOUR METER

2

51147 6413441032-14 PF-4410 43147 20311833

1.0 CYLINDER, TR

1.0 519.29 .0000 519.29

42147 210

SHOP LABOR

6.5 65.66 .0000

426.79

SUB-TOTAL FREIGHT

946.08 55.75

GRAND TOTAL

1,001.83

TERR: 641-000-100 SMAN: 641-1501-100 TERR: 000-000-000 SMAN: 000-0000-000 TERR: 000-000-000 SMAN: 000-0000-000

Case 1:04-cv-10328-GAO Document 21-3 Filed 12/23/2004 Page 9 of 19

INVOICE/CREDIT MEMO: 641-03703
INVOICE DATE: 12/09/03

ORIGINAL INVOICE NBR:

I-R ORDER NBR: 641-6284 W

DATE SHIPPED:

VIA: PREPAID

TERMS: NET 30 DAYS CUST PO NBR:

INGERSOLL-RAND EQUIPMENT SALES

NC 28275

P O BOX 75697

CHARLOTTE

300 TURNPIKE RD RTE9

TEL: (508) 481-1350

ES SHIP FROM:

E O BOX 13091

INGERSOLL-RAND EQUIPMENT SALES

SOUTHBORO MA 01772

CUSTOMER NBR: 790-100495

TAX: 39-02-00-00,000 T4

00000

INGERSOLL-RAND COMPANY BLAW KNOX (919) 750 BROADWAY AVENUE EAST

MATTOON IL 61938

00N IL 61938

PCODE PART NUMBER / DESCRIPTION QUANTITY UNIT PRICE DISCOUNT TOTAL AMOUNT

AUGER SHUT OFF PROBLEMS. REAR LIGHTS. BRAKE ACTING UP COMES ON.

WITE IN ADDITIONAL LIGHT CIRCUIT. EACH PAIR OF LIGHTS NOW ON THEIR OWN CIRCUIT. TEST LIGHTS FOR 2 HOURS REMOVED AND REPLACED L/H AUGER REOSTAT. CHECK AND ADJUST FORCE MOTORS FOR MAX SPEED AND SHUT OFF CREEPING CHECK BRAKE FUNCTIONS AND SWITCH.

ARRIVED AT LOSSITE PEARING LIVE NUCLES CONVEYOR.

ARRIVED AT JOBSITE. READJUST L/H AUGER CONVEYOR FORCE MOTOR IN AUGER WAS CREEPING WHEN HOT OBSERVE MACHINE PAVING NO AUGER CREEP WHEN HOT.

FAILURE DATE - 11/18/3
REPAIR DATE - 11/26/3
IN SERVICE - 5/5/3

HOUR METER - 335

51147 6413441032-14	PF-4410	1.0	.0000	
43147 20934477	RHEOSTAT	1.0	36,40	36.40
43147 20934576	SWITCH	1.0	13.30	13.30
42147 210	SHOP LABOR	16.0	65.66 .0000	1,050.56
42147 215	FIELD LABOR	1.0	65.66 .0000	65.66
42147 230	TRAVEL TIME	1.0	65.66 .0000	65.66
42147 233	TRAVEL MILEAGE	25.0	1.90 .0000	47.50

SUB-TOTAL 1,279.08 GRAND TOTAL 1,279.08

TERR: 641-000-100 SMAN: 641-1501-100
TERR: 000-000-000 SMAN: 000-0000-000
TERR: 000-000-000 SMAN: 000-0000-000

QUANTITY	PART#	DESCRIPTION
		•



Ingersoll-Rand Equipment and Services Company '300 Turnpike Road Southboro, MA 01772 508-481-1350

Work Order	<u>(28</u>	4
TECH:	Odas	M

Warrarby	•
CUSTOMER: Murry Pauling CALL LOCATION:	CONTACT NAME: Arule PHONE NUMBER
DATE W/O OPENED:	508 820 7244 PO NUMBER
MODEL: 4410 HOURS:	S/N: 3214

DESCRIPTION OF WORK PERFORMED:

Lyt Feel augus Rt 135	@ loplater / arlland line - (white (hurch)
	BONE

AT YOUR REQUEST, INGERSOLL-RAND AGREES TO PERFORM THE ABOVE SPECIFIED REPAIR WORK. MINIMUM CHARGE WILL BE 1 HOUR AT CURRENT LABOR RATES. IF THE NECESSITY FOR ANY FURTHER REPAIR IS DISCOVERED IN THE COURSE OF COMPLETING THE WORK, YOU WILL BE ADVISED OF THIS AS WELL AS THE ADDITIONAL COST. UNLESS AGREED TO OTHERWISE IN ADVANCE, THE TOTAL AMOUNT DUE WILL BE PAID IN FULL AT THE TIME THE EQUIPMENT IS PICKED UP. IF REQUIRED, YOU WILL BE RESPONSIBLE FOR ANY TRANSPORTATION OF YOUR EQUIPMENT TO AND FROM OUR SHOP. WE WILL ALLOW FIVE (5) DAYS AFTER YOU ARE NOTIFIED OF COMPLETION OF REPAIRS TO PICK UP THE EQUIPMENT. AFTER THIS TIME STORAGE CHARGES MAY BE ASSESSED. EQUIPMENT DESIGN CORRECTIONS OR MODIFICATIONS ARE NOT COVERED BY THIS CONTRACT. UNLESS EXPRESSLY AGREED TO OTHERWISE IN WRITING AND ATTACHED HERETO, THE REPAIR WORK SHALL BE GOVERNED BY THE TERMS AND CONDITIONS, MAINTENANCE AND REPAIR CONTRACT.

I HERBY AGREE TO PAY ON DELIVERY FOR ALL LABOR, REPAIR PARTS AND MATERIAL USED AT YOUR CURRENT RATES IN PERFORMING THE ABOVE REPAIR WORK ON MY EQUIPMENT.

THE UNDERSIGNED CERTIFIES THAT HE HAS THE AUTHORITY TO BIND THE ABOVE NAMED OWNER BE IT A CORPORATION, PARTNERSHIP, OR PROPRIETORSHIP AS TO ALL NECESSARY CHARGES WITH RESPECT TO THE ABOVE REPAIRS

Υ	
OWNER OR AGENT'S SIGNATURE	X UNIT PICKED UP BY

YTITÄAUÇ	p,	ART#	, . n	ESCRIPTION	-
4=	00133	911-00	South Sand		
	00133-	966-00	SWITCH	> RF 68517	Per 11 PC 1
(7)	00133	-940-00	REUSTAT	- /	reg W13)
			•		
		· · · · · · · · · · · · · · · · · · ·			
				-	
`,					
	./				
				·	
			. 3		
			2)		·
		- No.			
					
					
		·			
					



Ingersoll-Rand Equipment and Services Company 300 Turnpike Road Southboro, MA 01772 508-481-1350

Work Order 6284

TECH: John M

Warranty			
CUSTOMER: MURAY Pave	2	CONTACT NAME: Arma	
CALL LOCATION:	:	PHONE NUMBER \$20 7244	
DATE W/O OPENED:		PO NUMBER	
MODEL: PF-4410	HOURS: 335	S/N: 3214	
		641 344 1032-14	
	DESCRIPTION OF WORK	PERFORMED:	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
	obleas		
2) Rear Lights			
3) Brake acting up ((comes ov) - clears u	with roset	
Tr.		- ANK	
WIRE W'	ADDITION LIGA	IT SECUT- FACH PAIR OF	
LIGHTS NOW CHOOKER OWN CIRCUIT			
- TEST LIGHTS FOR 2 HOURS-OK			
DRER 1/H/	AUGIER REOSTA,		
- CHECK & AD	TUST FORCE 1	MOTORS FOR MAX SPEND	
£ 5HII	- OFF CREEPI		
B) - CHIECK BRAKE FUNCTIONS & SWITCH			

AT YOUR REQUEST, INGERSOLL-RAND AGREES TO PERFORM THE ABOVE SPECIFIED REPAIR WORK. MINIMUM CHARGE WILL BE 1 HOUR AT CURRENT LABOR RATES. IF THE NECESSITY FOR ANY FURTHER REPAIR IS DISCOVERED IN THE COURSE OF COMPLETING THE WORK, YOU WILL BE ADVISED OF THIS AS WELL AS THE ADDITIONAL COST. UNLESS AGREED TO OTHERWISE IN ADVANCE, THE TOTAL AMOUNT DUE WILL BE PAID IN FULL AT THE TIME THE EQUIPMENT IS PICKED UP. IF REQUIRED, YOU WILL BE RESPONSIBLE FOR ANY TRANSPORTATION OF YOUR EQUIPMENT TO AND FROM OUR SHOP. WE WILL ALLOW FIVE (5) DAYS AFTER YOU ARE NOTIFIED OF COMPLETION OF REPAIRS TO PICK UP THE EQUIPMENT. AFTER THIS TIME STORAGE CHARGES MAY BE ASSESSED. EQUIPMENT DESIGN CORRECTIONS OR MODIFICATIONS ARE NOT COVERED BY THIS CONTRACT. UNLESS EXPRESSLY AGREED TO OTHERWISE IN WRITING AND ATTACHED HERETO, THE REPAIR WORK SHALL BE GOVERNED BY THE TERMS AND CONDITIONS, MAINTENANCE AND REPAIR CONTRACT.

I HERBY AGREE TO PAY ON DELIVERY FOR ALL LABOR, REPAIR PARTS AND MATERIAL USED AT YOUR CURRENT RATES IN PERFORMING THE ABOVE REPAIR WORK ON MY EQUIPMENT.

THE UNDERSIGNED CERTIFIES THAT HE HAS THE AUTHORITY TO BIND THE ABOVE NAMED OWNER BE IT A CORPORATION, PARTNERSHIP, OR PROPRIETORSHIP AS TO ALL NECESSARY CHARGES WITH RESPECT TO THE ABOVE REPAIRS

X	
OWNER OR AGENT'S SIGNATURE	_

(R) Ingersoll Rand

300 Turnpike Road, Route 9 Southboro, MA 01772 (508) 481-1350 Fax: (508) 487-2014

EQUIPMENT CHECK IN/OUT

Date 1/-18-03 In Out
Customer Market
Model PE711110
S/N 321/1
Fuel SZ14
Hours > 70 CUSTO MEN UNIT
Comments
- For repair work
ID Ölmak
Customer Signature
K L

	5683661	1886	
V		soli Rand	WH MA
(508) 481-1350	565140un		300 Turnpike Road outhboro, MA 01772
CUSTOMER:	MURRI	y Palu	NG
ADDRESS:	00B S	TIE	·
	HOPINGTO	W HWY!	35
TELEPHONE: _		DATE: _	11-26-03
TIME LEFT	TIME ARRIVED ON JOB	TIME <u>LEFT JOB</u>	TIME ARRIVED
HOME []	0	0 1	HOME []
SHOP #	8.30 Am	930 Am	SHOP 1000 Am
MOTEL EQUIPMENT MO	inei ce	RIAL NUMBER	MOTEL HOUR METER READING
DE	2/1) 447	1030-14	HOUR METER READING
WORK PERFORMED:	SITUET	1/4 1.	<u> </u>
- RE-1	r7/Vs/US/	4/17 <i>19491</i> 2	2 /Convieye
FORCE	Moroe	11.	
AUGER	WAS CR	EEPING 1	WHEN Ho
- OBSERI	E MAC	HINE PA	MAG SO
Augres	CREKER	WHEN A	100
	<u></u>		
EXPENSES	TIME CHARGED	SERVICEMAN'S SIGNATURE	16-
MEALS	SUNDAY	× Cloves.	M FOUN
LODGING	WEEKDAY	CUSTOMER'S PURCHASE ORDI	ER NUMBER
TEL	OVERTIME		2
TRANS.EXP.	MILEAGE	SERVICEMAN'S SIGNATURE	
OTHER	MILES 25	×///////////	
)

INGERSOLL-RAND EQUIPMENT SALES

300 TURNPIKE RD RTE9

SOUTHBORO

MA 01772

TEL: (508) 481-1350

INVOICE/CREDIT_MEMO: 641-03737 INVOICE DATE: 12/16/03

ORIGINAL INVOICE NBR:

I-R ORDER NBR: 641-6194 W

DATE SHIPPED:

VIA:

PREPAID

TERMS: NET 30 DAYS

CUST PO NBR:

INGERSOLL-RAND EQUIPMENT SALES

P O BOX 75697

SHIP FROM:

CHARLOTTE

NC 28275

CUSTOMER NBR: 790-100495

TAX: 39-02-00-00.000 T4

INGERSOLL-RAND COMPANY

BLAW KNOX (919)

750 BROADWAY AVENUE EAST

MATTOON

IL 61938

00000

PCODE PART NUMBER / DESCRIPTION

QUANTITY UNIT PRICE DISCOUNT TOTAL AMOUNT

LIGHTS GOING OUT. AUGER NOT STOPPING. UNIT RECEIVED WITH FOLLOWING DISCREPANCIES. CIRCUIT WILLNOT HOLD AND LEFT AUGER HAS INTERNAL ELECTRICAL PROBLEMS. LIGHTING CIRCUIT SPLIT INTO 2 CIRCUITS. SUSPECTED OVERLOAD PROBLEM. AUGER CIRCUIT BREAKER LOOSE POST, REPLACE AND TIGHTEND TEST RUN.

12/ 1/ 3 FAILURE DATE -

REPAIR DATE -12/ 1/ 3 5/ 5/ 3 IN SERVICE

HOUR METER 2

51147 6413441032-14 PF-4410

1.0.0000 43147 20934576

SWITCH 1.0 -13.30 13.30 42147 210 SHOP LABOR 16.5 65.66 .0000 1,083.39

> SUB-TOTAL 1,096.69 GRAND TOTAL 1,096.69

TERR: 641-000-100 SMAN: 641-1501-100 TERR: 000-000-000 SMAN: 000-0000-000 TERR: 000-000-000 SMAN: 000-0000-000



Ingersoll-Rand Equipment and Services Company 300 Turnpike Road Southboro, MA 01772 508-481-1350 Work Order 6194

TECH:

John M

CUSTOMER:	(warresty)	641-	979783	
	ustruction (Paving)	CONTAC	Arus	
DATE W/O OPENED:	lo 63	PHONE N 50 PO NUMB) ሄ ሄ ያረ) - ንን ዛረ	
PF 4410	HOURS 326	S/N: 3?	214	
	•	641	3441032-14	

DESCRIPTION OF WORK PERFORMED:

1) See attached Sheet
A) Unit recircul with Following discrepancies -> Lat circuit will not hold and left auger B) I cold in the control problems. (Slut aff.)
F-141 51711 N/S CIPCUS COLC 1
c) Augu circuit breater loose post - replace and tighten test row ADK (vibration suspect)
adete
CO_{UV}

AT YOUR REQUEST, INGERSOLL-RAND AGREES TO PERFORM THE ABOVE SPECIFIED REPAIR WORK. MINIMUM CHARGE WILL BE 1 HOUR AT CURRENT LABOR RATES. IF THE NECESSITY FOR ANY FURTHER REPAIR IS DISCOVERED IN THE COURSE OF COMPLETING THE WORK. YOU WILL BE ADVISED OF THIS AS WELL AS THE ADDITIONAL COST. UNLESS AGREED TO OTHERWISE IN ADVANCE, THE TOTAL AMOUNT DUE WILL BE PAID IN FULL AT THE TIME THE EQUIPMENT IS PICKED UP. IF REQUIRED, YOU WILL BE RESPONSIBLE FOR ANY TRANSPORTATION OF YOUR THE EQUIPMENT TO AND FROM OUR SHOP. WE WILL ALLOW FIVE (5) DAYS AFTER YOU ARE NOTIFIED OF COMPLETION OF REPAIRS TO PICK UP COVERED BY THIS CONTRACT. UNLESS EXPRESSLY AGREED TO OTHERWISE IN WRITING AND ATTACHED HERETO, THE REPAIR WORK SHALL BE GOVERNED BY THE TERMS AND CONDITIONS, MAINTENANCE AND REPAIR CONTRACT.

HERBY AGREE TO PAY ON DELIVERY FOR ALL LABOR, REPAIR PARTS AND MATERIAL USED AT YOUR CURRENT RATES IN PERFORMING THE USED AT YOUR CURRENT RATES IN PERFORMING THE

HE UNDERSIGNED CERTIFIES THAT HE HAS THE AUTHORITY TO BIND THE ABOVE NAMED OWNER BE IT A CORPORATION, PARTNERSHIP, OR ROPRIETORSHIP AS TO ALL NECESSARY CHARGES WITH RESPECT TO THE ABOVE REPAIRS

MER OR AGENT'S SIGNATURE

UNIT PICKED UP BY

•	y ·	
QUANTITY	PART # 🧠	DESCRIPTION
	PART# 00133 -966-00	SWITCH RF 68272
		The River
· ·		
	``	
		<i>f</i>

(IP) Ingersoll Rand

300 Tumpike Road, Route 9 Southboro, MA 01772 (508) 481-1350 Fax: (508) 487-2014

EQUIPMENT CHECK IN/OUT

Date	1/-6-03 In Cout
Custome	MUCKAV Paving
Model	PF 44/10
S/N	32/4
Fuel	customer unit
Hours -	326
Commen	Light; 5 going out
=	Auger not stoping
	Arnle
	506-8207744
IR Signati	F, R, LK
Customer	Signature \mathcal{H} , \mathcal{B}